

## PREVENTIVE MAINTENANCE

### **Periodic Inspection:**

All bolts should be periodically inspected to ensure there are no loose connections.

Swivels should be periodically inspected to ensure that adequate grease is present on all bearing surfaces. Grease swivels as needed.

Glides should be periodically inspected for wear, and worn glides should be replaced as needed.

Frame welds should be periodically inspected for wear. Any damaged frames should be noted and removed from the floor for replacement.

## UNSURPASSED COMFORT

 Gary Platt Manufacturing  
4643 Aircenter Circle  
Reno, Nevada 89502-5948

 [www.garyplatt.com](http://www.garyplatt.com)

 Toll-Free Phone: 800-969-0999  
 Toll-Free Fax: 800-757-0788

Connect with us on social!

