



GARY PLATT[®]
S E A T I N G

PREVENTIVE MAINTENANCE

Periodic Inspection:

All bolts should be periodically inspected to ensure there are no loose connections.

Swivels should be periodically inspected to ensure that adequate grease is present on all bearing surfaces. Grease swivels as needed.

Glides should be periodically inspected for wear, and worn glides should be replaced as needed.

Frame welds should be periodically inspected for wear. Any damaged frames should be noted and removed from the floor for replacement.

SEATING ELEVATED

 Gary Platt Seating
175 Salomon Circle,
Suite 103, Sparks, Nevada 89434

 Toll-Free Phone: 800-969-0999
Toll-Free Fax: 800-757-0788

 www.garyplatt.com

Connect with us on social!

